

## 2.2.3.14 Philippines - Mindanao General Santos International Airport

Operator: Civil Aviation Authority of the Philippines (International Airport) - (in 2008 – Pax 302,887, Cargo 8,943 MT, Movement 2,348) – Magnetic Variation 000 E (01/06) – PCN 073FCWT – ILS – Beacon - Runway 17 (Heading 173.0) Take off distance increased to 3,352m (overrun Concrete pad 126m), Lighting HIRL / A2 / PAPI, slope -0.4 – Runway 35 (Heading 353.0) Take off distance increased to 3,352m (overrun concrete pad 126m), Lighting HIRL / PAPI, slope +0.4.

**Caution: Mount Matutum (2,286m – 7,500') 18NM N of the airport. Airport Beacon HO. RESTRICTION: VFR OPERATION ONLY, CLSD TO NORDO.**

Operating hours: 2300 – 0700Z. Fuel available (Jet A1, JetA1 with icing inhibitor, NC-A1). Communications: TWR 118.1, 255.4 / RDO 6802.5, 3671 / APP 119.1, 118.2 – Navaid: Type VOR-DME, ID GSA, Name TAMPLER, Channel 092X, Freq 114.5, at Airport, Coordinates Lat 06 04' 32.42" N Long 125 05' 31.87" E.

GES - RPMR

Airport Details			
Country	Philippines – UTC + 8	Latitude	6.058003
Province / District	South Cotabato, Mindanao	Longitude	125.096
Airport Name	General Santos International Airport, Tambler Airport	Elevation (ft)	505
IATA & ICAO codes	GES - RPMR	Surface	Concrete
Town or City (closest)	Barangay Fatima and Barangay Tambler, General Santos City	Runway Condition	GOOD however to be confirmed before landing
NGO / UN (on ground)	n/a	Passenger / Cargo Security Screening (Yes / No)	n/a
Runway Dimension	3,227 m x 45 m	Ground Handling (Yes / No)	n/a
Refueling Capacity	n/a	Runway Lighting (Yes / No)	Yes
Runway Heading	n/a	Fire Fighting Equipment (Yes / No)	n/a
Air Traffic Control (Yes / No)	n/a	Windsock (Yes / No)	n/a
Weather Information (Yes / No)	n/a	Aircraft Parking space (Yes / No)	n/a
Navigation Aids (Yes / No)	n/a	Perimeter fencing (Yes / No)	n/a