

2.2.2.14 Philippines - Visayas Borongan Airport

Operator: Air Transportation Office (Feeder Airport) - Magnetic Variation 000 W (01/06) – NO ILS – Runway 02 (Heading 021.0) – Runway 20 (Heading 201.0).

Caution runway 02 – 20 temporally closed due to lack of runway markers.

Operating hours: Sunrise to Sunset (SR-SS). Nil permanent communications. No Navaid.

Airport Details			
Country	Philippines – UTC + 8	Latitude	11.67433
Province / District	Samar, Eastern Samar	Longitude	125.4788
Airport Name	Borongan	Elevation (ft)	7
IATA & ICAO codes	BPR - RPVW	Surface	Concrete
Town or City (closest)	Barangay Punta Maria, Borongan	Runway Condition	Currently close due to lack of runway markers
NGO / UN (on ground)	n/a	Passenger / Cargo Security Screening (Yes / No)	n/a
Runway Dimension	1,199 m x 29 m	Ground Handling (Yes / No)	n/a
Refueling Capacity	n/a	Runway Lighting (Yes / No)	No
Runway Heading	n/a	Fire Fighting Equipment (Yes / No)	n/a
Air Traffic Control (Yes / No)	n/a	Windsock (Yes / No)	n/a
Weather Information (Yes / No)	n/a	Aircraft Parking space (Yes / No)	n/a
Navigation Aids (Yes / No)	n/a	Perimeter fencing (Yes / No)	n/a