

Milling Assessment

Milling Company: Özmermer Un San. Ve Tic A.Ş.

We, as Özmermer Flour, produce wheat flour with daily 450 Tons capacity with 28 years' experience in Gaziantep/Turkey.

We produce all-purpose flour (multipurpose flour), French bread/baguette flour, pita bread flour, lavash/tortilla flour, cake-pastry flour, phyllo flour and baklava flour. We export flour to the Middle East, Africa and Latin America. We export flour in 5 kg, 10 kg, 15 kg, 25 kg and 50 kg PP and in 1 kg, 2 kg and 5 kg craft as package options.

Company Name and Address	Contact Names and Email	Telephone and Fax
Özmermer Un San. Ve Tic A.Ş. 4. Organize San. Bölgesi 83426 Nolu Cd. No. 10/1A Şehitkamil / Gaziantep / TÜRKİYE	Name: Hasan Özmermer Title: Vice president Email: hasan@ozmermerun.com Web: https://www.ozmermerun.com/	Tel: +905324137056 Fax:
Summary of Role and Services		

Facilities	
Parking Area Inside Compound (m²)	3000 m ²
Drainage	Good
Fire Fighting Equipment	69 Fire tube / 17 Fire cabinet
Number of Ventilators (screened)	11 steel silos have a ventilation system Ventilation is done with an open window system in the factory.
Electricity Load (KVA)	2500 KVA
Backup Generator(s)	Yes 90 KVA

Milling Equipment			
Origin of Machinery	Year of Mfg	Year of Installation	Condition
TURKEY	2013	2013	Good

Maintenance			
Duration	4 Hours /1 Week	Type of Maintenance	Mechanical

Other Equipment or Machinery Installed				
Type of Equipment	Available	Number	Owned	Comments
Fortification Feeder	Yes	3	Yes	
Bag Cleaning Plant	Yes	12	Yes	
Moisture Tester	Yes	2	Yes	
De-stoning Plant	Yes	2	Yes	
Metal Extractor	Yes	27	Yes	

Staffing	
Number of Full Time Skilled Workers	41
Number of Full Time Labourers	44

Weighbridge				
Number		Capacity (MT)	Length (m)	Type
	1			

Within Compound	60 MT	16 M	Tunaylar
Within Compound			

Building			
	Length (m)	Width (m)	Height (m)
Building – Wheat Mill	180 M	80 M	30 M
Building – Maize Mill			
Walls	Brick		
Roof	Reinforced concrete		
Floor	Steel		

Conditions & Cleanliness		
	Outside	Inside
Cracks in Walls or Roof	No	Yes, there are some Due to the earthquake And we are working to repair them. risk-free document was given to the building by the state.
Signs of Rodent Activity	No	No
Signs of Birds Entry	No	No
Damaged Gutters/Drains	No	No
Signs of Moisture	No	No
Adjacent Vegetation	No	No
Cleanliness	Good	Good

Pest Control					
Fumigation	Yes	Frequency	Yearly	Contracted	Yes
Spraying	Yes	Frequency	Monthly	Contracted	Yes
Rodenticides	Yes	Frequency	Weekly	Contracted	Yes
Rodent Trapping	Yes	Frequency	Weekly	Contracted	Yes

Security	
Security	Good
Compound	Fenced
Other Comments	We have two 2 side protection plus Camera

Access	
Distance from Main Town (<i>km</i>)	20 KM
Travel Time if not Located in Town (<i>hours</i>)	15-20 min
Road Condition to Mill	Asphalt double lane smooth road
Road Limitations (if any)	NO
Rail Connections	No
On the Railway From	To
Other Comments	

Milling Capacity		
Commodities	Daily Capacity (<i>MT</i>)	Monthly Activity (<i>MT</i>)
Wheat	600 MT	18000 MT

Maize		
--------------	--	--

Storage Capacity		
Storage in Metric Tons	Wheat – Covered (MT)	Flour – Covered (MT)
Within the Compound	8000 MT	5100MT
Outside the Compound	48500 MT	

Capacity to Blend
30 MT / HOUR

Loading & Discharge Rates
75 MT / HOUR

Transport Capacity at Mill
450 MT / DAY

Additional Notes